

DEVIZ PRESTARI SERVICII

Data: 20/11/2019 8:11:09AM

Client:
PRIMARIA ORAS IERNUT
Adresa:
Adresa livrare:
Tel/Fax: Mobil:
E-mail: iernut@cjmures.ro
C.U.I. RO5584644
Nr. Inreg. Reg.Com. 0
Banca:
IBAN:
Persoana contact:
Telefon persoana de contact

Informatii autovehicul:
Marca/Model: FORD / MICROBUS
Combustibil: Diesel
An fabricatie:
Numar inmatriculare: MS-09-CLI
Numar identificare: WF0LXXGBFL2J11470
Culoare: GALBEN
Index kilometraj: 420000

Alte specificatii:

Data inchidere deviz: 20.11.2019
Comanda reparatii nr. 31517 din
20.11.2019
ITP la zi?
Data expirare ITP:

Obs.:

Estimare:

Cost total estimat: **1,427.00**, Revizuit:
Data promisa: 20/11/2019 8:10:16AM

Nr. Crt.	Cod Piesa / Manopera	Denumire Piesa / Manopera	Cantitate
Manopera			
1	OP_737	REGLAT UNGHI DE FUGA AUTOUTILITARA	
2	OP_522	INLOCUIT BIELETA DIIRECTIE	
3	OP_522	INLOCUIT BIELETA DIIRECTIE	
4	OP_27	D/R BRAT INFERIOR	
5	OP_27	D/R BRAT INFERIOR	
6	OP_484	INLOCUIT CAP DE BARA	
7	OP_484	INLOCUIT CAP DE BARA	
8	OP_635	INLOCUIT ROLA INTINZATOR	

Total Manopera

Materiale			
9	FTD568W	FTS BUCSA FATA FTD568W	2.00
10	FFZ2057	FTS BIELETA DIRECTIE FFZ2057	1.00
11	FFZ2172	FTS BIELETA DIRECTIE FFZ2172	1.00
12	FJBU718	FTS BUCSA AXA FATA FJBU718	2.00
13	F36515FE	FTS BURDUF DIRECTIE F36515FE	1.00
14	F36517FE	FTS BURDUF DIRECTIE F36517FE	1.00
15	FJTE1044	FTS CAP DE BARA FJTE1044	2.00
16	FLMI29626	FTS PIVOT AXA FATA FLMI29626	2.00

Total Materiale

